

# SAFETY BULLETIN

SR005311003

MURPHY AIRCRAFT MFG. Ltd.,  
8155 AITKEN ROAD,  
CHILLIWACK,  
B.C.  
CANADA V2R 4H5  
Tel: (604) 792-5855  
Fax: (604) 792-7006  
[Murtech@murphyair.com](mailto:Murtech@murphyair.com)

DATE: 31 October 2003

## AIRCRAFT AFFECTED: SUPER REBEL FAST BUILD FUSELAGES

Recent inspection of a Fast Build fuselage showed the required 9 rivets missing from the join between the roof bulkhead and the upright forming the rear doorpost at station 5. This is detailed in Chapter 9.2, page 33 para 26 of the main construction manual.

Please check your fuselage at Station 5 and Station 8 and install this 9 rivet pattern if it is missing. This may involve removing the rear top door space round corner gusset (FUS-37).