

Murphy Aircraft mfg. Ltd.

Unit 1, 8155 Aitken Road,
Chilliwack, British Columbia, Canada
V2R 4H5

Tel: (604) 792-5855

Fax: (604) 792-7006

Safety Bulletin 041797E

Date: Wednesday, March 18, 1997
Chilliwack, British Columbia

Attention: Elite Owners/Builders
Subject: Float Attach Doublers

Contact: **Technical Services**
 Murphy Aircraft Mfg. Ltd.
 Ph. 604-792-5855
 Fax. 604-792-7006
 e-mail murtech@murphyair.com

Information:

It was discovered that the float attach doublers, part number FUS-448 were incorrectly manufactured. the design has been modified and new ones will be sent shortly. Do not install these parts until you have received the new float attach doublers. Thank you very much and I apologize for any inconvenience,

[Home](#) | [Aircraft](#) | [Airshows](#) | [Our Story](#) | [Contact Us](#) | [Shipping](#) | [Technical Support](#)
[Education](#) | [Builder Directory](#) | [Builder Projects](#) | [Builder Completions](#) | [Links](#)

© Copyright 2004 Murphy Aircraft Mfg. Ltd.

